

# SPEC SHEET + MEASUREMENTS

*Brooks Brothers*

## Brooks Brothers® Wrinkle-Free Stretch Pinpoint Spread Collar Shirt. BB18012

### Product photo



This iconic dress shirt combines a little bit of stretch with a classic spread collar for a polished look. A premium wrinkle-free treatment process means effortless style and a sharp, professional finish all day long.

- 4.4-ounce, 97/3 cotton/spandex fine yarn count
- Taped seams
- Spread collar with removable stays
- Left chest pocket
- Pearlized buttons
- Rounded, adjustable single-button cuffs

**Care Instructions** Machine Wash Warm With Like Colors. Only Non-Chlorine Bleach, If Needed. Tumble Dry Low, Remove Promptly And Hang. Warm Iron, If Needed.

### Sketches



front



back

# SPEC SHEET + MEASUREMENTS



## Brooks Brothers® Wrinkle-Free Stretch Pinpoint Spread Collar Shirt. BB18012

### PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	29 1/2	30	30 1/2	31	31 1/2	32	32 1/2	33
Chest	19 1/2	21	22 1/2	24	26	28	30 1/2	33 1/2
Sleeve Length from Center Back	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39
Neck Circumference	15 1/2	16	16 3/4	17 1/2	18 1/4	19	19 7/8	20 7/8
Chest Pocket Height	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Chest Pocket Width	4 1/2	4 1/2	4 3/4	4 3/4	4 3/4	4 3/4	4 3/4	5

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

**Neck Circumference:** Measure from center of button to end of buttonhole along the center of the collar stand.

**Chest Pocket Height:** Measure from top to bottom at center.

# SPEC SHEET + MEASUREMENTS


*Brooks Brothers*

Brooks Brothers® Wrinkle-Free Stretch Pinpoint Spread  
Collar Shirt. BB18012

## SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-47	48-51	52-56	57-61
Neck	14 ½ - 15	15 - 15 ½	15 ½ - 16	16 - 16 ½	16 ½ - 17	17 - 17 ½	17 ½ - 18	18 - 18 ½
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2

## HOW TO MEASURE



**Neck** Measure around the fullest part of the neck at the base.  
**Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## COLORS



Cobalt Blue



Deep Black  
PMS BLACK  
C



Newport Blue  
PMS 7681C



White  
PMS WHITE  
C